

Annexure D

BUILDING SAFETY CERTIFICATE

No. 227

Dated: 12/5/2026

It is certified that the existing building **Nirmala Convent School** (name of the building or premises) at **Khasra No. 2116-2122, Village Meerpura, Near Om Farm House, Shikarpur Bypass Road, Bulandshahr, U.P. 203001** (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the						
Block	-	-	G+2	-	-	-

The building is owned/occupied by **Nirmala Convent School** (name of the Institution) have complied with the building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Assistant Engineer** (Name of Department/ Govt.) on **12.05.2026** (date of inspection) in the presence of **Mohit Kumar** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **2026** for a period of **2 years** in accordance

with rule and subject to compliance of the specific conditions as appended.

1. The Work has been completed to my best satisfaction.
2. The Workmanship & all the materials have been used strictly in accordance with general and detailed Satisfaction.
3. The Building is Structurally sound, safe and hygienic.
4. Hence it is fit for use how with Nirmala Convent School.

Issued on **12.05.2026** at **BULANDSHAHR** by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail

Signature with Seal: _____

Name: Mohit Kumar

Designation: _____

Name & Address of Department/ Office: उत्तर प्रदेश सरकार, बुलंदशहर


Principal
Nirmala Convent School
Shikarpur By Pass Road
Bulandshahr (U.P.) 203001


MANAGER
NIRMALA CONVENT SCHOOL
SHIKARPUR BYE PASS ROAD
BULANDSHAHR (U.P.)